




Maria Bostenaru Dan (Autor)  
**Housing in Bucharest, Romania**  
An Analysis of Vulnerability to Earthquakes



<https://cuvillier.de/de/shop/publications/762>

Copyright:  
Cuvillier Verlag, Inhaberin Annette Jentsch-Cuvillier, Nonnenstieg 8, 37075 Göttingen,  
Germany  
Telefon: +49 (0)551 54724-0, E-Mail: [info@cuvillier.de](mailto:info@cuvillier.de), Website: <https://cuvillier.de>

# CONTENTS

<b>Acknowledgements</b> .....	8
<b>Introduction: The built substance of Bucharest</b> .....	9
2. Site survey .....	14
<b>2.1. Mapping the impact</b> .....	15
<b>2.2. Surveyed characteristics</b> .....	16
3. Typological survey .....	18
<b>Before 1850:</b> .....	35
<b>Eclecticism:</b> .....	36
One family one storey house, also called "wagon house" (#85)	
.....	37
<b>General Information</b> .....	38
<b>Architectural features</b> .....	39
<b>Socio-economic issues</b> .....	41
<b>Structural features</b> .....	44
<b>Evaluation of Seismic Performance and Seismic</b>	
<b>Vulnerability</b> .....	49
<b>Earthquake Damage Patterns</b> .....	55
<b>Building Materials and Construction Process</b> .....	56
<b>Construction Economics</b> .....	64
<b>Insurance</b> .....	66
<b>Seismic Strengthening Technologies</b> .....	66
<b>Pictures</b> .....	75
<b>Romanian Art Nouveau:</b> .....	96
A single-family, two-storey house with brick walls and timber	
floors (#84) .....	98
<b>General Information</b> .....	99
<b>Architectural Features</b> .....	100
<b>Socio-Economic Issues</b> .....	102
<b>Structural Features</b> .....	104
<b>Evaluation of Seismic Performance and Seismic</b>	
<b>Vulnerability</b> .....	107
<b>Earthquake Damage Patterns</b> .....	112
<b>Building Materials and Construction Process</b> .....	112
<b>Construction Economics</b> .....	116
<b>Insurance</b> .....	116
<b>Seismic Strengthening Technologies</b> .....	116
<b>Pictures</b> .....	121
<b>Multistorey masonry house</b> .....	131
<b>General Information</b> .....	131
<b>Architectural Features</b> .....	132

<b>Socio-Economic Issues</b> .....	134
<b>Structural Features</b> .....	136
<b>Evaluation of Seismic Performance and Seismic Vulnerability</b> .....	138
<b>Earthquake Damage Patterns</b> .....	142
<b>Building Materials and Construction Process</b> .....	143
<b>Construction Economics</b> .....	146
<b>Insurance</b> .....	146
<b>Seismic Strengthening Technologies</b> .....	146
<b>Pictures</b> .....	150
<b>Romanian Avant-Garde:</b> .....	155
Early reinforced concrete frame condominium building with masonry infill walls designed for gravity loads only (#96) ....	156
<b>General Information</b> .....	157
<b>Architectural Features</b> .....	159
<b>Socio-Economic Issues</b> .....	161
<b>Structural Features</b> .....	164
<b>Evaluation of Seismic Performance and Seismic Vulnerability</b> .....	173
<b>Earthquake Damage Patterns</b> .....	180
<b>Building Materials and Construction Process</b> .....	183
<b>Construction economics</b> .....	198
<b>Insurance</b> .....	200
<b>Seismic Strengthening Technologies</b> .....	201
<b>Pictures</b> .....	209
Building of the Modern Movement - with commercial ground floor .....	225
<b>General Information</b> .....	227
<b>Architectural Features</b> .....	228
<b>Socio-Economic Issues</b> .....	229
<b>Structural Features</b> .....	232
<b>Evaluation of Seismic Performance and Seismic Vulnerability</b> .....	237
<b>Earthquake Damage Patterns</b> .....	243
<b>Building Materials and Construction Process</b> .....	246
<b>Construction economics</b> .....	254
<b>Insurance</b> .....	256
<b>Seismic Strengthening Technologies</b> .....	256
<b>Pictures</b> .....	264
<b>1940-1950:</b> .....	278
Reinforced concrete frame structure with diagonal bracings and brick infill walls (#71) .....	279

<b>General Information .....</b>	<b>280</b>
<b>Architectural Features .....</b>	<b>281</b>
<b>Socio-Economic Issues.....</b>	<b>282</b>
<b>Structural features.....</b>	<b>284</b>
<b>Evaluation of Seismic Performance and Seismic</b>	
<b>Vulnerability .....</b>	<b>286</b>
<b>Earthquake Damage Patterns.....</b>	<b>290</b>
<b>Building Materials and Construction Process .....</b>	<b>290</b>
<b>Construction Economics .....</b>	<b>295</b>
<b>Insurance .....</b>	<b>295</b>
<b>Seismic Strengthening Technologies .....</b>	<b>295</b>
<b>Pictures .....</b>	<b>299</b>
<b>International Style (1945-1977): .....</b>	<b>309</b>
Reinforced concrete cast-in situ shear wall buildings ("OD"-type, with "fagure" plan) (#78).....	310
<b>General Information .....</b>	<b>311</b>
<b>Architectural Features .....</b>	<b>312</b>
<b>Socio-Economic Issues.....</b>	<b>313</b>
<b>Structural Features .....</b>	<b>315</b>
<b>Evaluation of Seismic Performance and Seismic</b>	
<b>Vulnerability .....</b>	<b>318</b>
<b>Earthquake Damage Patterns.....</b>	<b>323</b>
<b>Building Materials and Construction Process .....</b>	<b>323</b>
<b>Construction Economics .....</b>	<b>327</b>
<b>Insurance .....</b>	<b>327</b>
<b>Seismic Strengthening Technologies .....</b>	<b>327</b>
<b>Pictures .....</b>	<b>331</b>
Block of flats with 11 floors out of cast-in-situ concrete, gliding frameworks (#87).....	339
<b>General Information .....</b>	<b>340</b>
<b>Architectural Features .....</b>	<b>341</b>
<b>Socio-Economic Issues.....</b>	<b>342</b>
<b>Structural Features .....</b>	<b>345</b>
<b>Evaluation of Seismic Performance and Seismic</b>	
<b>Vulnerability .....</b>	<b>347</b>
<b>Earthquake Damage Patterns.....</b>	<b>352</b>
<b>Building Materials and Construction Process .....</b>	<b>353</b>
<b>Construction Economics .....</b>	<b>357</b>
<b>Insurance .....</b>	<b>358</b>
<b>Seismic Strengthening Technologies .....</b>	<b>358</b>
<b>Pictures: .....</b>	<b>362</b>

<b>Romanian Socialist Architecture (1977-1990):</b>	379
Precast concrete panel apartment buildings (#83)	380
<b>General Information</b>	381
<b>Architectural Features</b>	382
<b>Socio-Economic Issues</b>	383
<b>Structural Features</b>	386
<b>Evaluation of Seismic Performance and Seismic Vulnerability</b>	389
<b>Earthquake Damage Patterns</b>	393
<b>Building Materials and Construction Process</b>	394
<b>Construction Economics</b>	397
<b>Insurance</b>	397
<b>Seismic Strengthening Technologies</b>	397
<b>Pictures:</b>	399
<b>Contemporary styles:</b>	405
Medium/high rise moment resisting reinforced concrete frame buildings (#97)	406
<b>General Information</b>	406
<b>Architectural Features</b>	407
<b>Socio-Economic Issues</b>	409
<b>Structural Features</b>	411
<b>Evaluation of Seismic Performance and Seismic Vulnerability</b>	413
<b>Earthquake Damage Patterns</b>	418
<b>Building Materials and Construction Process</b>	419
<b>Construction Economics</b>	423
<b>Insurance</b>	424
<b>Seismic Strengthening Technologies</b>	424
<b>Pictures:</b>	427
<b>CV</b>	450